



The Service Group



APRIL 2010 SHODA TECHNICAL BULLETIN


This month I have a crucial topic that needs to be addressed as most machines still have their original Mitsubishi PLC back up batteries installed. If battery fails Machine PLC will be lost upon power down of machine. These batteries need to be replaced ASAP and you will want to keep a record of replacement date. Please pay special attention to notes below.

Topic: Mitsubishi PLC Backup battery replacement. (Hitachi PLC not necessary)

Location: Left side of Mitsubishi PLC in Electrical Cabinet.

CAUTION: PLC needs to be backed up prior to Battery replacement. Special Software needed to perform this procedure. This procedure should be performed by a Qualified Technician only or verify with TSG if PLC back up has been performed.

Extreme Caution: Battery replacement must be performed with power on. Shock Hazard.



Note: Caution needs to be used when purchasing new replacement battery. Many batteries have the same part number as this battery but are not a direct replacement for this specific battery.

Please Contact TSG for more information on this Battery and procedure. This procedure is performed during a TSG PM Inspection.

Cody J. Featherston
V.P. of Operations

3707 168th ST. NE Suite 1
P.O. Box 3646
Arlington Wa. 98223
360-659-5263 Fax: 360-651-1039
www.theservicegroup.us Email general@theservicegroup.us